

SCA (Stream Corridor Assessment) Survey Report

Inspector: Masaya Maeda
Anacostia Watershed Society
Mar 30, 2004



(GPS data: 38.98285N, -76.99949W)

- Sewer pipe running along the stream and manhole stack.
- The stack has cracks (see picture down below) on top of it and one can see inside of stack.
- Potential leakage problem, especially during high flow events
- Potential problem of damage by a high flow event and possible sewage release



- Encircled: major cracks



- Connecting pipe is exposed



- Being undermined

This page left blank