

# SCA (Stream Corridor Assessment) Survey Report

Inspector: Masaya Maeda  
Anacostia Watershed Society  
Apr. 07, 2004

## Problem

Riverbed upstream of an exposed pipe is pushing the pipe and the pipe is in danger of being disconnected. It is likely that there is leakage, though it cannot be seen clearly with naked eye. This pipe is also a fish barrier.

## Location

N38°59.667'  
W77°00.252'



021105

