

# SCA (Stream Corridor Assessment) Survey Report

Inspector: Masaya Maeda  
Anacostia Watershed Society  
Apr. 22, 2004

## Problem

Cracked manhole stack. Collapse may occur if it is hit by big trees etc. during a storm event. This is also a fish barrier. Sewage pipe should not be exposed. Manhole stack should not be in the stream.

## Location

N38°58.318'  
W76°58.933'







